

# Technical Data Sheet



## CK98 AIR CONTROL KITS

### Pneumatic Controls

Designed for modern truck cabs, with a compact design, the momentary controls are VSB6 Version 3.2 Section J4 compliant for body mounted tippers.

These controls are manufactured to exacting tolerances ensuring consistent, trouble-free operation.

Hydreco Powauto produces a wide variety of controls dependent on your requirements. From hoist only to the most complex truck and trailer assembly.

Configured for discreet fitment – ordering the right control for your truck cab is easy.

#### Suits:

Truck hoist applications

Truck and trailer applications

## Product Features

- **Integral Plastic Body**  
Engineering plastics technology for accuracy and repeated cycles of operation.
- **Brackets and Pedestals With CK Kits**  
Use with or without, depending on requirements.
- **Light**  
Visual check when PTO is engaged and auxiliary function operated.
- **Pre Packaged System Kit**  
Provides easy installation.
- **Auto Disengage for PTO**  
Prevents damage to your transmission due to prolonged engagement.  
(Some models only)




**HYDRECO**  
a member of **DAIKIN** group



[www.hydreco.com](http://www.hydreco.com)

# Technical Data Sheet



Kit Part	Control Only	Functions	Mounting	Features
CK98A	73150	PTO - Hoist	Pedestal	Auto PTO Disengage
CK98C	73151	PTO - Hoist	Pedestal	No Auto PTO Disengage
CK98E	73151	PTO - Hoist	Pedestal	No Auto PTO Disengage - 6mm
CK98M	73150	PTO - Hoist	Pedestal	Auto PTO Disengage - 6mm
CK98G	73155	PTO - Hoist	Pedestal	Auto PTO Disengage - Momentary
CK98B	73160	PTO - Hoist	Pedestal	No Auto PTO Disengage - Momentary
CK98D	73155	PTO - Hoist	Pedestal	Auto PTO Disengage - Momentary 6mm
CK98F	73160	PTO - Hoist	Pedestal	No Auto PTO Disengage - Momentary 6mm
	73152	Hoist Only	Bracket	Control Only
	73153	PTO - Hoist	Bracket	2 Bank Control Switch
	73154	PTO - Hoist - Auxilliary	Bracket	3 Bank Control Switch
	73159	PTO Only	Bracket	Single Control Switch

Indicates Control is VSB6 Ver3.2 Section J4 compliant for body mounted tippers

Spares: RK017—Knob Repair Kit.

Doc: CK98—07/23



**HYDRECO**  
a member of **DAIKIN** group



[www.hydreco.com](http://www.hydreco.com)